MAHONING COUNTY

STRUCTURE

Smith Twp.

Bandy Road C.H. 17 Structure No. 24

Located 1295 feet North of Benton W. Road #68

Length	Size	Material	Distance from C.L. Lt. Rt.
36'	12"	RCP	Headwalls None

Skew None Lt. ☐ Rt. ☐ Side forward

Field Book Date

Depth of fill over top 3'10"

Direction of Flow East

Drainage Area

REMARKS: Separation on both ends needs repaired
2530' from N. Benton to ℄ of W. Reserve Rd. #32

REPAIRS

YEAR	DESCRIPTION
1974	Poor