MAHONING COUNTY

# STRUCTURE

MILTON Twp.

DUCK CREEK Road C.H. 53 Structure No. 53

Located 979 feet SOUTH of S.R. #18

10031 NORTH PALMYRA ROAD C.H.136

| Length | Size | Material | Distance from C.L. | Lt. | Rt. |
|---|---|---|---|---|---|
| 20' | 10" | CIP | 13' | 12' | |

Skew NONE Lt. ☐ Rt. ☐ Side forward

Headwalls CUT STONE-EAST

Depth of fill over top 12"

Field Book 169 Date

Drainage Area

Direction of Flow WEST

REMARKS: RIP RAP ON LEFT. WEST END BLOCKED AND BURIED. DETRIMENTAL INSTEAD OF USEFUL UNLESS THERE IS A SPRING UNDER ROADWAY

REPAIRS

| YEAR | DESCRIPTION |
|---|---|
| | |
| | |
| | |
| | |
| | |
| | |
| | |