MAHONING COUNTY

STRUCTURE

(Struthers) & ~~Poland~~ Twp.

Fifth Avenue Road C.H. 197 Structure No. 2

Located 455 feet north of S.R.616

Length	Size	Material	Distance from C.L. Lt. Rt.
	12"	V.S.P.	Headwalls

Skew Lt. ☐ Rt. ☐ Side forward Field Book Date

Depth of fill over top Direction of Flow

Drainage Area

REMARKS: City Sewer System

REPAIRS

YEAR	DESCRIPTION