MAHONING COUNTY

STRUCTURE MILTON Twp.

GRANDVIEW BLVD Road C.H. 33 Structure No. 15A

Located 265 feet NORTH C of CULVERT #15

Length	Size	Material	Distance from C.L. 22' Lt. 22' Rt.
44'	15"	RCP	Headwalls NONE

Skew NONE Lt. ☐ Rt. ☐ Side forward Field Book Date

Depth of fill over top 48" Direction of Flow EAST

Drainage Area

REMARKS: Structure was constructed in 1958

REPAIRS

YEAR	DESCRIPTION