MAHONING COUNTY

STRUCTURE MILTON Twp.

GRANDVIEW BLVD Road C.H. 33 S Structure No. 18

Located 830 feet SOUTH of MAHONING-TRUMBULL LINE

Length 40' Size 18" Material RCP Distance from C.L. Lt. Rt.

Headwalls LOOSE STONE

Skew NONE Lt. ☐ Rt. ☐ Side forward Field Book 128 Date

Depth of fill over top 12" Direction of Flow EAST

Drainage Area

REMARKS: Structure was constructed in 1958

REPAIRS

YEAR	DESCRIPTION