MAHONING COUNTY

STRUCTURE

MILTON Twp.

GRANDVIEW BLVD Road C.H. 33 Structure No. 7

Located 150 feet SOUTH of DAVIS RD

Length	Size	Material	Distance from C.L. 25' Lt. 25' Rt.
50'	24"	RCP	Headwalls NONE

Skew NONE Lt. ☐ Rt. ☐ Side forward Field Book 128 Date

Depth of fill over top 18" Direction of Flow EAST

Drainage Area

REMARKS: Structure was constructed in 1958

REPAIRS

YEAR	DESCRIPTION