MAHONING COUNTY

STRUCTURE

Austintown Twp.

Kirk Road C.H. 146 Structure No. 25

Located 1862 feet East of Turner RD.

Length	Size	Material	Distance from C.L. 11'6" Lt. 15'6" Rt.
27'	26"x16"	STONE BOX	Headwalls None

Skew None Lt. ☐ Rt. ☐ Side forward

Field Book Date

Depth of fill over top

Direction of Flow

Drainage Area

REMARKS: Needs cleaned, repaired, washed out.

REPAIRS

YEAR	DESCRIPTION
1970	Poor
1985	REPAIRED HEADWALL & CLEANED INLET & OUTLET