MAHONING COUNTY

STRUCTURE

Milton Twp.

Mah.-Trumbull Co. Line Road C.H. 4 Structure No. 9

Located 9157 feet East of Mah. Co. Line Rd.

Length	Size	Material	Distance from C.L.	Lt.	Rt.
24'LT.	15"	RCP- LT.	Headwalls None		

Skew 30° Lt. ☐ Rt. ☐ Side forward

Field Book Date

Depth of fill over top 3'9"

Direction of Flow South

Drainage Area

REMARKS: 1940' East of Grandview Rd. Outlet buried

REPAIRS

YEAR	DESCRIPTION
1972	LT Good RT. Poor