MAHONING COUNTY

# STRUCTURE

Smith Twp.

Martin Road C.H. 13 Structure No. 1 thru 4A

Located ..... feet ..... of .....

| Length | Size | Material |
|---|---|---|
| | | |

Distance from C.L. ..... Lt. ..... Rt. .....

Headwalls .....

Skew ..... Lt. ☐ Rt. ☐ Side forward

Field Book ..... Date .....

Depth of fill over top .....

Direction of Flow .....

Drainage Area .....

REMARKS: Culverts 1 thru 4A are out. Keller Mining Co (coal) and Standard Slag Co (Limestone) are working this section of Martin Rd. This part of Section A will be restored when work ends.

REPAIRS

| YEAR | DESCRIPTION |
|---|---|
| 1974 | |
| | |
| | |
| | |
| | |
| | |
| | |