MAHONING COUNTY

STRUCTURE

Smith Twp.

North Benton West Road C.H. 68 Structure No. 11

Located East ~~feet~~ Inter. of Bandy Rd. #17

Length	Size	Material	Distance from C.L. 26' Lt. 26' Rt.
52'	12"	R.C.P.	Headwalls None

Skew Straight Lt. ☐ Rt. ☐ Side forward

Field Book 327-326A Date

Depth of fill over top

Direction of Flow South

Drainage Area

REMARKS: Structure was constructed in 1949

REPAIRS

YEAR	DESCRIPTION